
Unilever Building

Location: Villa Elisa, Paraguay







Architect: Solano Benitez

Owner: Unilever

Year of completion: 2001

Climate: Koppen Climate Cfa

Material of interest: Ceramic Brick

Application: Exterior/Interior

Properties of material: The exterior shell is made out of prefabricated brick panels, allowing for a hollow appearance while providinf structure.

Sources:

Freitas, Anderson, and Pablo Hereñú. Solano Benítez. São Paulo: Hedra, Editora Da Cidade, 2012. Print.

Images:

http://abcblogs.abc.es/fredy-massad/files/2014/04/ Edificio-Unilever-Paraguay2.jpg

http://66.media.tumblr.com/tumblr_mc22fh8wDh1qa-t99uo1_r1_1280.jpg

https://s-media-cache-ak0.pinimg.com/736x/19/f0/58/19f0585368e69c4dd25ee948c7105f78.jpg