

Guru Bar

case study
By Margina Demmer

Location: Athens, Greece



Architect: KLab Architects

Owner: N/A

Year of completion: N/A

Climate: Mediterranean Climate

Material of interest: Rusted Steel

Application: Exterior

Properties of material: The rusting material of the façade is a metaphor for the transformation in a deteriorating phase. The building is also transformational with the kinetic movement of steel plates that open to form window shutters and doors.

Sources:

Architect Website: www.klab.gr/en