

Temppeli aukio Kirkko (Rock Church)

case study
By Emily Rosa

Location: Helsinki, Finland



Architect: Timo and Tuomo Suomalainen

Owner: n/a

Year of completion: 1969

Climate: Hemiboreal Climate

Material of interest: Unworked Rock

Application: Exterior

Properties of material: Unworked rock is used on the exterior and interior of this church, which allows it to fit into the context where it is buried in a piece of granite. The rock also creates desirable acoustics inside the space.

Sources:

<http://www.sacred-destinations.com/finland/helsinki-rock-church-temppeli aukio> http://en.wikipedia.org/wiki/Temppeli aukio_Church

<http://www.toursdart.com/CurrentTours.htm>, http://www.placesonline.com/europe/finland/travel_guide.asp

<http://thehive.com/2012/07/02/a-church-built-in-a-giant-piece-of-granite-do-tell-12-hq-photos/>