


# Shanghai Hongqiao Performing Arts Center

case study  
By Ziwen Wang

Location: Changning District, Shanghai, China



Architect: BAU

Owner: Shanghai Changning Cultural Bureau

Year of completion: 2016

Climate: Humid subtropical climates

Material of interest: Glass

Application: Exterior

Properties of material:  
Solid, brittle and transparent.  
Some level of reflective.

Sources:

ArchDaily: <http://www.archdaily.com/797245/an-assemblage-of-difference-shanghai-hongqiao-performing-arts-center-bau>